

## LANDLORD/HOME OWNER GAS SAFETY RECORD Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations 1998.

|   |               |  |                         |                        |                                   |      |               |  |                            |                                       | C                     | Certificate Reference: |          |                               |  | RB00115                                 |            |               |                |
|---|---------------|--|-------------------------|------------------------|-----------------------------------|------|---------------|--|----------------------------|---------------------------------------|-----------------------|------------------------|----------|-------------------------------|--|---|------------|---------------|----------------|
| DETAILS OF THE CONTRACTOR                                       |               |  |                         |                        |                                   |      |               | DETAILS OF THE INSTALLATION                    |                            |                                       |                       |                        | D        | DETAILS OF THE CL             |  |   | ′LAN       | DLORD         |                |
|   |               | <ul> <li>Priority Home Service Limited</li> <li>Unit 4, Neepsend Triangle</li> </ul> |                         |                        |                                   |      |               | Installa<br>Address                            | 93                         | Rented<br>93 onslow road<br>Sheffield |                       |                        |          | ldress:                       | West One Accomodation (West One)<br>14 Fitzwilliam Street<br>Sheffield |   |            |               |                |
|   |               | 1 Burton Road<br>Sheffield   |                         |                        |                                   |      |               |  | SIR                        |                                       |                       |                        |          |                               | ,  | memeru                                  |            |               |                |
|   |               | Post Code: S3 8BW  |                         |                        |                                   |      |               | Post Code: S 11                                |                            |                                       |                       |                        |          | Post Code: S1 4JL             |  |   |            | 4JL           |                |
| Gas Safe No:  |               | 539093 Tele  |                         | phone No: 0330 9991999 |                                   |      | Telepho       | one No:  | ):                         |                                       |                       |                        |          | elephone N                    | lo: 01142722400  |   |            |               |                |
| APPLIANCE DETAILS   |               |  |                         |                        |                                   |      |               |  |                            |                                       |                       |                        |          |                               |  |   |            |               |                |
|   | Location      |  |                         | Appliance Type         |                                   |      |               |  | Make                       |                                       |                       | Model                  |          | Flue Type                     | Landlord's Ap  | oliance                                 |            |               |                |
| 1   | Bed Ro        | d Room   |                         |                        | Chb                               |      |               | Idea   | I                          |                                       |                       | Logic plus combi 3     |          | bi 30                         | 30 RS Yes  |   | Yes        |               | Yes            |
| 2   |               |  |                         |                        | ]                                 |      |               |  |                            |                                       |                       |                        |          |                               |  |   |            |               |                |
| 3   |               |  |                         |                        |                                   |      |               |  |                            |                                       |                       | ]                      |          |                               |  |   |            |               |                |
|   |               |  |                         |                        |                                   |      |               |  |                            |                                       |                       |                        |          |                               |  |   |            |               |                |
|   | Combu         |  |                         |                        | Safety Devices(s) Ventilation Pro |      |               | ovision  | vision Visual Condition of |                                       |                       | Flue Appliance         |          |                               | pliance  | AUDIBLE CO ALA<br>Approved CO Is CO ala |            |               | esting of CO   |
|   | Analy<br>Read | ding   | in mbar<br>heat input i | n kW                   | Correct Ope                       |      | Satisfacto    |  | Satis                      | Termination<br>factory                | Performa<br>Test      |                        | Serviced |                               | afe To<br>Use  | alarm fitted                            | in date    | ala           | m satisfactory |
| 1   | 000           | 0007 31.01   |                         |                        | Yes                               |      | Yes           |  | Yes                        |                                       | N/A                   |                        | Yes      | s Yes                         |  | Yes                                     | Yes        |               | Yes            |
| 2   |               |  |                         |                        |                                   |      |               |  |                            |                                       |                       |                        |          | -                             |  |   |            |               |                |
| 4   |               |  |                         |                        |                                   |      |               |  |                            |                                       |                       |                        |          | +                             |  |   |            |               |                |
| DEFECT(S) I DENTIFIED REMEDIAL ACTION TAKEN                     |               |  |                         |                        |                                   |      |               |  |                            |                                       |                       |                        |          | ][_                           |  |   | <br>N      | OTICE & LABEL |                |
| 1   |               | ,  |                         |                        |                                   |      |               | <mark>·</mark>                                 |                            |                                       |                       |                        |          |                               |  |   |            | ISSUED        |                |
| 2   |               |  |                         |                        |                                   |      |               |  |                            |                                       |                       |                        |          |                               |  |   |            |               |                |
| 3   | 1             |  |                         |                        |                                   |      |               |  |                            |                                       |                       |                        |          |                               |  |   |            |               |                |
| 4   |               |  |                         |                        |                                   |      |               |  |                            |                                       |                       |                        |          |                               |  |   |            |               |                |
|   |               |  |                         |                        |                                   |      |               |  |                            |                                       |                       |                        |          |                               |  |   |            |               |                |
| Outco   | me of ga      | as insta   | Illation pipew          | ork visu               | al inspectio                      | n P/ | ASS Is the Er | nergency Control Valve access satisfactory YES |                            |                                       |                       | YES                    | Οι       | Outcome of gas tightness test |  |   |            | PASS          |                |
| Outcome of gas supply pipework visual inspection PASS Is the Pr |               |  |                         |                        |                                   |      |               |  | Equipote                   | ential bondir                         | ding satisfactory YES |                        | YES      |                               | NEXT INSPECTION DUE<br>ON OR BEFORE:                                   |   | 23/06/2016 |               |                |
| SI GI   | <b>NATUF</b>  | RES  | Report Issue            | d By:                  | Name:                             |      | Rich Baker    |  | Sign                       | ed:                                   | (SR                   |                        |          | Date I                        | nspected:  | 23/06/2015                              | Gas ID     | No:           | 3498362        |
| Report Received By: Name:                                       |               |  |                         |                        |                                   |      |               |  | Sign                       | ed:                                   |                       |                        |          | Date F                        | Received:  |   |            |               |                |