

LANDLORD/HOME OWNER GAS SAFETY RECORD Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations 1998.

											C	ertific	ate Refere	ence:	KBC	00258	
DETAILS OF THE CONTRACTOR						DETA	ILS	OF THE IN	STALLA	IO IT.	N	D	ETAILS	OF THE CL	_I ENT/L	ANDLO	RD
Trading Title: Priority Home Service Limited Address: Unit 4, Neepsend Triangle 1 Burton Road Sheffield					Installation Address: Rented 18c Newbould Lane Sheffield							West one lettings 134 whitham road Sheffield					
Post Code: S3 8BW							1	Post Code:	S10	2PL				Post Code	e: S10 2SF	3	
Gas Sa	afe No: 5390	93 т	elephone No: 03	30 9991999		Telephone No						Telephone No		0:			
APPLIANCE DETAILS																	
		Aj	Appliance Type				Make		Model			Flue Type	Landlord's Appliance		Appliance Inspected		
1	Kitchen		СНВ			Alph	ia			He C	B 25		RS	Yes		Yes	
2																	
3																	
4																	
LNSE	PECTION D	FTALLS										AUDI BLE (O AL AF	N/			
	Combustion Analyser Reading	Operating Pressur in mbar or heat input in kW	Correct Opera		ntilation Pro Satisfactor		Flue ar	I Condition of and Termination atisfactory	Flue Performa Test	nce	Appliance Serviced		ppliance afe To Use		Is CO alarn in date		
1	0003,7.4,30				Yes			Yes			No		Yes	Yes	Yes	Ye	es es
2																	
3																	
4																	
DEFI	ECT(S) ID	ENTIFIED						REMEDI A	AL ACTI	ON 1	TAKEN		·			NOTI CE IS:	E & LABEL SUED
1																	
2																	
3																	
4																	
_										VEC						DACC	
Outcome of gas installation pipework visual inspection PASS Is the En						mergency Control Valve access satisfactory YES					Outcome of gas tightness test					PASS	
Outcome of gas supply pipework visual inspection PASS Is the Pr						otective Equipotential bonding satisfactory				YES		NEXT INSPECTION DUE ON OR BEFORE:			07/12/2016		
SIGNATURES Report Issued By: Name: Rich Baker			h Baker		Sig	gned:	d: (5)		Dat		nspected:	07/12/2015	Gas ID N	io: 349	98362		
Report Received By: Name:						Signed:					Date R	ate Received:					
Report	printed using	Tysoft EasyGas -	Copyright Tysoft	2015 - Ga	as Safety ((Installa	tion ar	nd Use) Regula	ations 199	8						Page: _	