

LANDLORD/HOME OWNER GAS SAFETY RECORD Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations 1998.

| | | | | | | | | | | | Certificate Reference: | | | MJ00000024 | |
|---|---------------------------|------------------------------------|--------------------------------------|--------------------------------------|------------------|-------------------------|---|----------------------|--------------------------|-----------------|------------------------|--|--------------------------|------------------------------|----------------------------------|
| DETAILS OF THE CONTRACTOR | | | | | | | DETAILS OF THE INSTALLATIO | | | | | DETAILS | OF THE C | LI ENT/L | ANDLORD |
| Trading Title: Priority Home Service Limited | | | | | | Installatio | | Installation Address | | | | Client Address: | | | |
| Address: | | Unit 4, Neepsend Triangle | | | | | Flat B 210 Broomhall Street | | | | | | | | |
| | | 1 Burton Road | | | | | Sheff | | ıı Street | | | | | | |
| | | Sheffield | | | | | Shen | ieiu | | | | | | | |
| | | Post Code: S3 8BW | | | | | | 1 | Post Code | : S3 7SC | 2 | | | Post Code: | |
| Gas Saf | Gas Safe No: 53909 | | 9093 Telephone No: 0330 9993 | | | Telephone No: | | | | | | Telephone N | No: | | |
| APPLIANCE DETAILS | | | | | | | | | | | | | | | |
| | | Location | | Appliance Type | | | 1 | Make | | Model | | Flue Type Landlord's Ap | | opliance Appliance Inspected | |
| 1 L | _iving F | ing Room | | СНВ | | Ideal | | | | Logic + Combi 2 | | 24 RS | Yes | | Yes |
| 2 | | | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | | | |
| INSPECTION DETAILS | | | | | | | | | | | AUDI BLE CO ALARM | | | M | |
| | Combus Analys Readi | er in | ng Pressure mbar or nput in kW | Safety Devices(Correct Operation | | ovision _{FI} | isual Conduction // is and Ter Satisfac | rmination | Flue Performa Test | ance Ap | opliance erviced | Appliance Safe To Use | Approved CO alarm fitted | Is CO alarm in date | Testing of CO alarm satisfactory |
| 1 9 | 9.6Co2/105ppi | /105ppm/0.0010 20.5mbar OP/26.11KW | | Yes | Yes | | Yes | | Pass | 5 | No | Yes | No | N/A | N/A |
| 2 | | | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | | | |
| DEFE | CT(S) | IDENTIF | ED | | | | REMEDIAL ACTION TAKEN | | | | | | | | NOTICE & LABEL ISSUED |
| 1 | | | | | | | | | | | | | | | |
| 2 | | | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | |
| Outcome of gas installation pipework visual inspection PASS Is the E | | | | | | | mergency Control Valve access satisfactory | | | ctory Y | ES | Outcome of gas tightness test PASS | | | |
| Outcome of gas supply pipework visual inspection PASS Is the Page 1997. | | | | | | | rotective Equipotential bonding satisfactory | | | tory Y | ES | NEXT I NSPECTION DUE ON OR BEFORE: 10/11, | | | 11/2016 |
| SIGN | ATUR | ES Report | ssued By: | Name: | Matthew Jacks | on | Signed: | | A | > | Dat | te Inspected: | 10/11/2015 | Gas ID No | o: 3700878 |
| Report Received By: Name: Signed: Date Received: | | | | | | | | | | | | | | | |
| Report p | rinted t | sing Tysoft Ea | asyGas - Co | pyright Tysoft 20 | 015 - Gas Safety | (Installatio | on and Us | se) Regula | ations 199 | 98 | | | | | Page: |